Maryland Historical Trust State Historic Sites Inventory Form

DOE __yes __no

Magi No.

1. Nam	le (indicate pr	eferred name)		
historic Fra	ame house			•
and/or common				
2. Loca	ation			
street & number	north side of San	dy Hook Bood OS -	ile and of Claule D	
-		dy Hook Road, .08 m		
	andy Hook	vicinity of	congressional district	sixth
state Maryla		county	Washington	
3. Clas	sification			
Category district building(s) structure site object	Ownership public private both Public Acquisition in process being considered not_applicable	Status X occupied unoccupied work in progress Accessible yes: restricted yes: unrestricted no	Present Use agriculture commercial educational entertainment government industrial military	museum park x private residence religious scientific transportation other:
4. Own	er of Prope	rty (give names a	nd mailing addresse	s of <u>all</u> owners)
name				
street & number			telephone no	o.:
city, town		state	and zip code	
5. Loca	ation of Leg	al Description	on	
courthouse, regis	stry of deeds, etc. Wasi	nington County Court	Thouse	
			.nouse	liber
street & number	Washington Stree	et		folio
	gerstown		state	Maryland
6. Repi	resentation	in Existing	Historical Surv	eys
title				
date			federal state	e county local
depository for su	rvey records			
city, town			state	

7. Description

Survey No. WA-III - 083

Condition excellent deteriorated good ruins fair unexposed	Check one unaltered x altered	Check one X original site moved date of move	
---	-------------------------------	---	--

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The frame house is a two-story frame structure constructed in a rectangular plan. It is three-bays by one-bay and constructed on a high stone foundation. The main facade is symmetrically arranged with a central entrance and six-over-six windows in the other bays. The structure has a two-bay front porch. The exterior is covered in asphalt siding imitating brick and has a gable roof. The high stone foundation provides a full story in front of the house which has a entrance in the bottom of the porch. The house appears to date from the mid-19th century.

The property is located on the north side of Sandy Hook Road, approximately .08 mile east of Clark Road, in Sandy Hook. The house sits back from the road on a level site. An early 20th century congrete block garden wall with ball ornaments surrounding the front of the site. The main facade faces south.

The two-story structure is constructed of frame covered in asphalt imitation brick siding. The high fieldstone foundation is painted white. The founda tion rises almost a full story on the main facade of the structure. This fullstory is covered in front by the porch and has a single entrance in the bottom section of the porch. The porch is a two-bay structure with a hipped roof that covers the easternmost two bays of the main facade. A side stair up to the porch is in the westernmost bay. The porch is supported by square posts and the railing as well as the bottom sections supporting the porch are covered in asphalt imitation-brick siding. The main facade has a central entrance. Six-over-six windows are located in the outer bays of the first story and the three-bays of the second story. These windows are also located in the single bay of the first and second story of the gable ends. A four-pane window is in each gable. The structure has a boxed cornice and a gable roof covered in sheet metal. An interior-end brick chimney rises from the east gable end. On the western most side of the house is a fieldstone retaining wall adjoining the foundation of the house that forms a small ornamental garden.

8. Significance			Survey No.WA-III- 083		
Period — preh — 1400 — 1500 — 1600 — 1700 — 1900	D-1499 archeology-historic D-1599 agriculture D-1699 architecture D-1799 art D-1899 commerce D communications		Iterature Iterat	religion science sculpture social/ humanitarian theater transportation	
Specific	dates Bu	uilder/Architect			
check:	Applicable Criteria: _A _ and/or Applicable Exception: _A _ Level of Significance: _ na	BCDE			
Prepare support	both a summary paragraph of			history and	

This site is a contributing structure in the Sandy Hook Survey District.

10.	Geographical	Data			
Quadran	of nominated property gle name erences do NOT complete		s	Quadrangle scale	
AZone	Easting Northing		B Zone	Easting Northing	
C E G			D		
Verbal	boundary description and jus	stification			
List all	states and counties for prop	erties overlappi	ng state or co	unty boundaries	
state		code c	ounty	code	
state		code c	county	code	
11.	Form Prepare	d By			
name/titl	e Joe Getty				
organiza	tion Maryland Historical	. Trust	dat	te April 1983	
street &	number 21 State Circle		tel	lephone	
city or to	Annapolis			ate Maryland	

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust

Shaw House

21 State Circle

Annapolis, Maryland 21401

(301) 269-2438

FREDERICK &

HARPERS FERRY, VA-MD-W VA | NGTON COMMONWEALTH OF VIRGINIA DIVISION OF MINERAL PERCURSION QUADRANGLE JAMES L. CALVER, STATE GEOLOGIST USGS 7.5 minute map 1:24 000 5462 I NW (KEEDYSVILLE) 1969 111-33



WA-III-083

5.

7. 1/1

- Washington Co., Md.
- 2.3. Joe Getty
- April 1983 7/82 4.

 - Md. Hist. Trust, Annapolis, Md.

- 6. South elev. (camera facing north)